

1965 APR 22 20 01Z

S E C R E T CITE NPIC 4328

1. CAMERA B 101 WAS USED IN MISSION 8012 FLOWN ON 20 APRIL 1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN. C

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: THE POSITION INDICATOR LAMP WAS INOPERATIVE
THROUGHOUT THE MISSION. THERE IS A CONTINUOUS MINUS DENSITY
STREAK 0.7" FROM AND PARALLEL TO THE INBOARD EDGE OF THE FILM 3,4
THROUGHOUT THE MISSION. THERE ARE MANUFACTURING SPLICES ON FRAMES
190, 1356 AND 2510. THERE ARE HEAT SPLICES ON FRAMES 353 AND
1468.

C. 9. SIDE: THERE IS A ROW OF PLUS DENSITY SPOTS NEAR THE INBOARD EDGE OF THE FILM THROUGHOUT THE MISSION. STATIC DISCHARGES OCCUR INTERMITTENTLY AT THE INBOARD EDGE OF THE FILM. A CONTINUOUS PLUS DENSITY STREAK, 2.16" FROM AND PARALLEL TO THE INBOARD EDGE OF THE FILM, IS PRESENT ON FRAMES 23 THROUGH 404. HEAT SPLICES ARE MADE IN FRAMES 404, 1624 AND BETWEEN FRAMES

[illegible]

202

--2--

1933/1934. THERE ARE MINOR CRIMPS AND PLUS DENSITY STREAKS ASSOCIATED WITH THE SPLICE IN FRAME 404. THE MANUFACTURER'S SPLICE MADE IN FRAME 1227 CAUSED A SLIGHT DENSITY BAND, EDGE TO EDGE, ON FRAME 1224.

D. BOTH SIDES: STATIC DISCHARGES OCCUR INTERMITTENTLY AT THE OUTBOARD EDGE OF THE FILM THROUGHOUT THE MISSION. SLIGHT FOGGING IS PRESENT ALONG THE INBOARD EDGE OF THE FILM THROUGHOUT. A WAVERING PLUS DENSITY STREAK OCCURS INTERMITTENTLY AND WITHIN 1.5" OF THE INBOARD EDGE OF THE FILM. A SLIGHT FLARE IS PRESENT ON EACH FRAME NEAR THE DATA CHAMBER. FRAMES ARE TITLED CONSECUTIVELY FROM 0001 THROUGH 2845.

E. THERE ARE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING PROBLEMS.

3. POSITIVE:

A PI SUITABILITY IS GOOD.

B PRINTING AND PROCESSING ARE GOOD.

C CLOUDS OBSCURE OR DEGRADE LESS THAN 5 PERCENT OF THE MISSION.

GP-1

S E C R E T

END OF MESSAGE